

IQ Engine 10.0r10 Release Notes

Release date: November 30, 2020

Hardware platforms supported: Atom AP30, AP122, AP122X, AP130, AP150W, AP230, AP245X, AP250, AP510C, AP510CX, AP550, AP630, AP650, AP650X, AP1130, and XR600P

Management platforms supported: ExtremeCloud IQ 20.11.50.1 and later

New Features and Enhancements

This release introduces the following new features and enhancements:

Wireless Visibility Enhancement: Devices, such as the AP150W, that have APs connected to the wired ports now collect wireless data from the APs and transmit the information to ExtremeCloud IQ.

Troubleshooting Command Set Enhancement: Administrators can now issue the `exec tcp-service` command on devices running IQ Engine 10.0r10. This command returns useful information regarding the TCP protocol stack.

Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.0.

Known Issues in IQ Engine 10.0r10

There are no known issues in this release.

Addressed Issues in IQ Engine 10.0r10

CFD-5569	Administrators could not configure a static WAN IP address using the NetConfig UI.
CFD-5552	The L7d service exceeded its memory allocation.
CFD-5525	Devices sometimes transmitted the same client trail information twice, resulting in duplicate rows in ExtremeCloud IQ.
CFD-5498	Client devices did not re-authenticate properly during roaming.
CFD-5460	Mobile clients were unable to authenticate through the captive web portal through some APs running IQ Engine 10.0r9a.
CFD-5448	AP650 access points could not reconnect to the network after a broadcast storm ended.
CFD-5396	Firewall rules did not upload properly to devices.
CFD-5387	AP250 access points were incorrectly generating CRC errors.
CFD-5340	AP650 access points sometimes falsely reported radar events when both radios were in 5 GHz mode.
CFD-5204	The radiusd service exceeded its memory allocation.

CFD-4608	Some APs became unresponsive during normal operation.
CVE-2019-3460 CVE-2019-3459 HOS-15307	Some versions of the Linux kernel were susceptible to allowing unauthorized access to attackers with sufficient physical access to establish a Bluetooth connection and transmit a special malformed packet.

Addressed Issues in IQ Engine 10.0r9b

CVE-2020-16152 HOS-15030	Attackers were able to exploit the web interface of devices running previous versions of IQ Engine to elevate privileges and to perform denial of service attacks.
-----------------------------	--

Addressed Issues in IQ Engine 10.0r9a

CFD-4802	Administrators could not retrieve tech data for AP1130 access points running HOS 10.0r8.
CFD-4710	Client devices sometimes disconnected because the VLAN changed during user profile reassignment.
CFD-4671	Remote sites lost VPN connection to VGVA, requiring administrators to restart the IPsec session.
CFD-4641	AP650 access points sometimes initiated a system core dump, and then rebooted or became unresponsive.
CFD-4005	When the XR600 router was used as a Layer 2 VPN server, TCP sessions within the tunnel sometimes closed unexpectedly.

Addressed Issues in IQ Engine 10.0r9

CVE-2019-15126 HOS-15944	Broadcom access points and wireless clients were vulnerable to traffic decryption during a very short time window during the dissociation process.
-----------------------------	--

Addressed Issues in IQ Engine 10.0r8

CFD-4471	When an admin configured an SSID to drop all non-management traffic destined for the ap, users were unable to authenticate to the network using PPSK self-registration.
CFD-4470	Wildcard characters did not function properly in walled garden captive web portals when NAT was enable on a user profile.
CFD-4453	Disconnecting a client from a WPA3 SSID caused all other clients to disconnect.
CFD-4422	In the output of different commands, IQ Engine reported different values for the same transmit power parameter.
CFD-4398	BLE iBeacons were inconsistently reported in the AP650 iBeacon monitor list output.
CFD-4309	AP650 access points rebooted soon after Cisco phones connected.
CFD-4300	When some APs were configured for scheduled reboot, Wi-Fi interfaces were shut down, preventing clients from reconnecting after the reboot.
CFD-4245	AP630 and AP650 access points were dropping a high number of packets.
CFD-4242	Some internal running processes of AP630 access points became unresponsive.
CFD-4190	AP1130 access point were rebooting spontaneously.
CFD-4126	When NTLMv1 was disabled in Active Directory, some access points were unable to act as RADIUS servers using PEAP with MS-CHAP-v2 authentication.

CFD-4086	Network users were sometime assigned to incorrect VLANs and RADIUS attributes were used for classification.
CFD-4085	IQ Engine was reporting high interference to ExtremeCloud IQ.