



# IQ Engine 10.0r9a Release Notes

**Release date:** August 14, 2020

**Hardware platforms supported:** Atom AP30, AP122, AP122X, AP130, AP150W, AP230, AP245X, AP250, AP510C, AP510CX, AP550, AP630, AP650, AP650X, and AP1130

**Management platforms supported:** ExtremeCloud IQ 20.8.1.1 and later

---

## New Features and Enhancements

This release introduces the following new features and enhancements:

**SD-WAN Tunnel Enhancements:** Routers and VGVA devices running IQ Engine 10.0r9a can now use one of three tunnel addressing settings:

- **Management Subnet (new default):** The device uses an address from the management subnet, which ensures that each device receives a unique WAN address.
- **WAN Address (former default):** The device uses the WAN address supplied by the WAN device, such as a cable or DSL modem.
- **Custom Address:** The administrator can define a pool of IP address for devices to use for the WAN address.

**VPN Gateway Enhancements:** Routers and VGVA devices running IQ Engine 10.0r9a and acting as a VPN gateway can now use ports other than the well known ports 500 and 4500 to terminate tunnels, allowing multiple VPN gateways to function behind a firewall.

---

## Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.0.

### Known Issues in IQ Engine 10.0r9a

There are no known issues in this release.

### Addressed Issues in IQ Engine 10.0r9a

CFD-4802	Administrators could not retrieve tech data for AP1130 access points running HOS 10.0r8.
CFD-4710	Client devices sometimes disconnected because the VLAN changed during user profile reassignment.
CFD-4671	Remote sites lost VPN connection to VGVA, requiring administrators to restart the IPsec session.
CFD-4641	AP650 access points sometimes initiated a system core dump, and then rebooted or became unresponsive.
CFD-4005	When the XR600 router was used as a Layer 2 VPN server, TCP sessions within the tunnel sometimes closed unexpectedly.

## Addressed Issues in IQ Engine 10.0r9

CVE-2019-15126 HOS-15944	Broadcom access points and wireless clients were vulnerable to traffic decryption during a very short time window during the dissociation process.
-----------------------------	--

## Addressed Issues in IQ Engine 10.0r8

CFD-4471	When an admin configured an SSID to drop all non-management traffic destined for the ap, users were unable to authenticate to the network using PPSK self-registration.
CFD-4470	Wildcard characters did not function properly in walled garden captive web portals when NAT was enable on a user profile.
CFD-4453	Disconnecting a client from a WPA3 SSID caused all other clients to disconnect.
CFD-4422	In the output of different commands, IQ Engine reported different values for the same transmit power parameter.
CFD-4398	BLE iBeacons were inconsistently reported in the AP650 iBeacon monitor list output.
CFD-4309	AP650 access points rebooted soon after Cisco phones connected.
CFD-4300	When some APs were configured for scheduled reboot, Wi-Fi interfaces were shut down, preventing clients from reconnecting after the reboot.
CFD-4245	AP630 and AP650 access points were dropping a high number of packets.
CFD-4242	Some internal running processes of AP630 access points became unresponsive.
CFD-4190	AP1130 access point were rebooting spontaneously.
CFD-4126	When NTLMv1 was disabled in Active Directory, some access points were unable to act as RADIUS servers using PEAP with MS-CHAP-v2 authentication.
CFD-4086	Network users were sometime assigned to incorrect VLANs and RADIUS attributes were used for classification.
CFD-4085	IQ Engine was reporting high interference to ExtremeCloud IQ.