

# IQ Engine 10.3r4 Release Notes

**Release date:** August 13 2021

**Hardware platforms supported:** Atom AP30, AP122, AP122X, AP130, AP150W, AP230, AP245X, AP250, AP302W, AP305C, AP305CX, AP410C, AP460C, AP460S6C, AP460S12C, AP510C, AP510CX, AP550, AP630, AP650, AP650X, and AP1130

**Management platforms supported:** ExtremeCloud IQ 21.3.10.1 and later

---

## New Features and Enhancements

This release introduces the following new features and enhancements:

**AirDefense Support Enhancements:** AP305C, AP305CX, AP510C, and AP510CX access points can now function as sensors in radio share mode. In Radio share mode, the radio functions as a sensor when it is not actively receiving and transmitting client WLAN traffic. When configured with an AirDefense server in an AirDefense on-premises environment, APs in radio share mode can use Air Termination to force clients to disconnect from the network.

**DTLS 1.2 Support:** Devices running IQ Engine 10.3r4 or later now support CAPWAP connections using DTLS 1.2. Using DTLS 1.2 to secure CAPWAP tunnels does not impact legacy Qualcomm devices.

**Mesh Improvements:** Meshed devices running IQ Engine 10.3r4 can now switch channels to clear the DFS channel more efficiently during a radar event.

**DNS Server Management:** When receiving a DNS request with an unresponsive primary DNS server, IQ Engine now chooses a secondary DNS server more quickly to prevent authentication timeouts. IQ Engines has also optimized how it handles changes in DNS ordering and configuration.

**DNS Security Enhancements:** IQ Engine DNS software has been hardened against recently revealed vulnerabilities, CVE-2020-25686, CVE-2020-25684, and CVE-2020-25685.

**AVC Signature Updates:** The Application Visibility and Control (AVC) signatures have been updated to include the latest Zoom application traffic.

---

## Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.3.

### Known Issues in IQ Engine 10.3r4

HOS-17309	AP410C access points sometimes become unstable and reboot.
-----------	--

HOS-17271	AP305C, AP302W, and AP510C access point cannot detect clients that are connected to a different BSS.  <b>Workaround:</b> To detect devices connected to neighboring networks, use promiscuous mode.
HOS-16843	Devices running IQ Engine 10.3r1 sometimes generate WIPS alarm messages for excluded channels.

## Addressed Issues in IQ Engine 10.3r4

CFD-6494	ExtremeGuest Essentials allowed non-employees to register as employees.
CFD-6481	Supplemental CLI Commands that were uploaded to devices were not functioning as expected.
CFD-6473	Wi-Fi interfaces sometimes became unresponsive and did not transmit data.
CFD-6154	AP650 access points sometimes restricted the data throughput of some applications so that some file transfers were slow.
HOS-16915	Wired Clients connected to a AP150W functioning as a router did not appear in the ExtremeCloudIQ client list.
HOS-16788	Transmit and Receive Byte count values did not match the values reported in ExtremeIoT and Client 360 View.

## Addressed Issues in IQ Engine 10.3r3

CFD-5858	AP250 access points sometimes became unresponsive and required a manual power cycle to recover.
CFD-5832	AP650 access points running IQ Engine 10.2r3 were spontaneously rebooting. This behavior might also affect AP510C access points.
CFD-5519	AP122 access points exhibited high CPU usage when ACSP was running.
HOS-17075	When an admin attempted to terminate a DFS channel BSS or client, the access point did not terminate the target.

## Addressed Issues in IQ Engine 10.3r2a

CFD-5719	For some tablet devices, the wireless connection was unstable when the devices were associated to AP305C access points.
HOS-17160	AP410C access points sometimes became unresponsive.

## Addressed Issues in IQ Engine 10.3r2

CFD-6092	The Eth1 port of the AP302W access point did not supply sufficient PoE power to supply some devices.
HOS-16837	The channel width on some APs did not change dynamically.
HOS-16833	Software Defined Radio (SDR) configurations sometimes did not upload successfully to the AP.
HOS-16793	AP302W wallplate access point experienced high packet loss and loss of connectivity after the admin enabled private client groups (PCG).

## Addressed Issues in IQ Engine 10.3r1

This is the inaugural release of IQ Engine 10.3.

