

HiveOS 8.2r8 Release Notes

Release date: July 27, 2020

Hardware platforms supported: AP122, AP122X, and AP150W

Management platforms supported: HiveManager Classic 8.2r2 and later

Known and Addressed Issues

Known Issues in IQ Engine 8.2r8

HOS-11615	An admin cannot add a new NAS (network access server) list unless the local RADIUS server is first disabled and then re-enabled.
HOS-11450	When tunneling wired guest traffic to a DMZ on an AP150W, the clients do not receive the appropriate IP address and tunneling is not successful. Workaround: Have clients connect to the wireless interfaces for tunneling guest traffic.
HOS-11138	Enabling Bonjour Gateway on an AP150W, AP122 or AP122X can cause those devices to report excessively high CPU loads. Workaround: Because Bonjour Gateway is a legacy feature, and is generally unnecessary, you can either disable Bonjour Gateway, or relocate Bonjour Gateways to a higher-powered access point such as an AP550.
HOS-11087	On the AP150W, if Client Monitor is performed against multiple clients concurrently, the access point occasionally loses the CAPWAP connection to ExtremeCloud IQ.
HOS-11004	Remote Packet Capture on the AP150W can only capture traffic from wireless interfaces.

Addressed Issues in IQ Engine 8.2r8

HOS-16364	Access points running IQ Engine 8.2r7 and earlier sometimes lost their radio calibration information.
-----------	---

Addressed Issues in IQ Engine 8.2r7

HOS-12634	Zero-wait DFS did not function properly in dual mode.
HOS-12259	Access points sometimes did not adjust transmit power in the presence of other access points.

Addressed Issues in IQ Engine 8.2r6

CFD-4059	ExtremeCloud IQ administrators could not fetch techdata files from access points.
----------	---

CFD-4043	IQ Engine Access-Requests for RADIUS admin auth did not use the correct Service-Type value of 'Administrative'.
CFD-4014	A file system error caused APs to reboot.

Addressed Issues in IQ Engine 8.2r5

CFD-3905	AP130 Wifi1 radio (5 GHz) sometimes stopped transmitting or receiving, resulting in loss of client connectivity.
CFD-3892	Wi-Fi radios of AP250 and AP550 access points were reinitializing spontaneously.
CFD-3882	MDM enrollment of mobile devices was unsuccessful.
CFD-3858	When disabled, the embedded web server continued to respond on the mgmt0 interface.
CFD-3836	Remote AP250 access points were unable to join domains.
CFD-3812	APs configured to use aggregate Ethernet interfaces required 802.11 at power, but were reporting using only 802.11af power, which resulted in unstable client connectivity.
CFD-3695	After upgrading from IQ Engine 6.5r10 to IQ Engine 8.2r4, AP230 access points were spontaneously rebooting and reverting back to IQ Engine 6.5r10.
CFD-3687	AP230 access points were spontaneously rebooting without apparent cause.
CFD-3673	DFS was enabled on AP1130 access points, even when DFS was disabled in the radio profile.
CFD-3667	AP130 access points running IQ Engine 8.2r3 were rebooting spontaneously.
CFD-3599	AP250 and AP550 access points were exhibiting high CPU utilization when using GRE tunnels.
CFD-3574	Client devices were losing connectivity when connected to AP150W access points on the 2.4 GHz interface.
CFD-3561	CRC error airtime percentage appeared with the incorrect value.
CFD-3549	The login success page redirection URL was used for both <i>Login Successful</i> and <i>Registration Successful</i> results.
CFD-3528	EIRP power displayed the incorrect value.
CFD-3516	The voice call setup process was unsuccessful because of an ARP cache IP address mismatch.
CFD-3459	64-bit values queried for the 1.3.6.1.2.1.31.1.1.1.10.6 OID using SNMP were truncated, leaving only the low-order 32 bits.

Addressed Issues in IQ Engine 8.2r4

CFD-3513	User groups that existed within nested OUs were not properly added for LDAP server attribute mapping.
CFD-3511	When an admin entered the <code>show station</code> command with ARP proxy disabled, the IP address of client devices that were connecting with a static IP address appeared as 0.0.0.0.
CFD-3472	Some devices running spectrum analysis incorrectly reported interference sources.
CFD-3470	When iPhones attempted to reconnect to an SSID with auto-join disabled, the AP sometimes returned the following error instead of connecting to the SSID: Incorrect password for <ssid>.
CFD-3461	Some outbound traffic to international subnets contained the IP address of the AP as the source address.

CFD-3460	When WMM was disabled on an SSID, AP122, AP130, and AP230 access points, clients were unable to associate to the SSID.
CFD-3439	SNMP did not function properly after rebooting the device when the SNMP server was configured to use the domain name.
CFD-3414	UPA (Use Policy Acceptance) authentication did not work properly when also using PPSK.
CFD-3396	The default captive web portal IP address redirected users to the Cloudflare DNS website.
CFD-3376	After updating IQ Engine devices to IQ Engine 6.5r9a, some users could no longer authenticate using 802.1X.
CFD-3265	Fragmented DNSv6 packets were not forwarded to the Wi-Fi interfaces.
CFD-2999	When connecting to a PPSK SSID after self-registering, the UPA captive web portal did not appear.

Addressed Issues in IQ Engine 8.2r3

CFD-3349	When exporting tech data, AP122 access points did not generate <code>show station</code> output.
CFD-3294	Ocasionaly, access points did not update successfully when static scanning channels were configured to include DFS channels.
CFD-3149	The Wifi0 interface sometimes did not respond properly to RTS frames sent by client devices.
CFD-3139	AP120 and AP230 access points sometimes spontaneously rebooted.
CFD-3129	In some cases, AP550 access points running IQ Engine 8.2r1 frequently rebooted.
CFD-2832	AP250 access points running IQ Engine 8.2r1 were rebooting spontaneously.
CFD-2781	AP550 access points erroneously reported high utilization, which appeared in the ExtremeCloud IQ spectrum analysis displays.
CFD-2644	AP230 access points classified 802.1p traffic properly, but did not properly classify some DiffServ traffic.
HOS-12634	Zero-DFS did not function properly on AP150W, AP250, and AP550 access points running IQ Engine 8.2r1.
HOS-12259	APs running IQ Engine 8.2r1 sometimes did not detect neighboring devices running on other channels during background scanning.

Addressed Issues in IQ Engine 8.2r2

CFD-3208	When using self-registration with captive web portal, the captive web portal did not appear on client devices running Android 7.1 or later, preventing successful registration.
CFD-3181	IQ Engine devices did not properly respond to some Disconnect-Request and Change-of-Authorization packets.
CFD-3155	ID Manager users were unable to authenticate because IQ Engine was using an incorrect IDM Proxy address.
CFD-3140 CFD-3129	AP550 access points sometimes spontaneously rebooted.
CFD-3139	AP130 and AP230 access point sometimes spontaneously rebooted.

CFD-3103	The ExtremeCloud IQ PPSK import process did not import email addresses that use the .asia domain.
CFD-3102	In some cases, Disconnect-Request and CoA packets were not processed properly, resulting in persistent retries.
CFD-3061	The RADIUS Service-Type attribute was not set properly within Access-Request and Accounting-Request packets.
CFD-3042	IP-Policy Layer 7 IPv6 rules whose source address value was "any" did not function properly.
CFD-3035	Devices running IQ Engine 8.1 sometimes raised alarms in ExtremeCloud IQ when using RADIUS with attribute mapping.
CFD-3034	HPE/Aruba ClearPass did not function properly when MAC authentication was used.
CFD-3017	IP address byte order in Layer 7 log entries was reversed.
CFD-3015	ExtremeCloud IQ allowed an admin to enter a 32-character user profile assignment group name, but returned an error.
CFD-3001	AP550 access points were not drawing the correct PoE power from the PSE when LLDP was enabled.
CFD-2945	The AP150W did not correctly negotiate 802.3at power levels when using LLDP-MED.
CFD-2910	Devices using the Taiwan country code (158) did not support DFS.
HOS-13111	Under certain circumstances when using RADIUS-based authentication, some wireless clients did not complete DHCP negotiations successfully, and did not acquire an IP address.
HOS-12459	AP550 access points sometimes assigned Wi-Fi radio channels with insufficient separation.

Addressed Issues in IQ Engine 8.2r1a

CFD-3076	AP245X access points operating on the 2.4 GHz band were experiencing very high airtime utilization in some regions.
CFD-3039	AP245X access points running IQ Engine 8.2r1 sometimes stopped forwarding client traffic to the network, resulting in a loss of client connectivity.
CFD-2980	Clients connected to some APs running IQ Engine 8.2r1 were experiencing intermittent packet loss on the 2.4 GHz band.
CFD-2973	Some devices were able to connect to AP230 and AP330 access points, but not to AP250 access points with a similar configuration.
CFD-2924	AP250 access points running IQ Engine 8.1r2a were experiencing high CPU utilization.

Addressed Issues in IQ Engine 8.2r1

HOS-11248	For the AP150W, the rate limiting settings for Eth2 and Eth3 did not appear after running a <code>show running config</code> command.
-----------	---