

HiveOS 8.4r10a Release Notes

Release date: March 8, 2019

Hardware platforms supported: Atom AP30, AP122, AP122X, AP130, AP150W, AP230, AP245X, AP250, AP550 and AP1130

Management platforms supported: HiveManager 19.2.1.2 or later

Known and Addressed Issues

Known Issues in HiveOS 8.4r10a

| | |
|-----------|---|
| HOS-14701 | The output power of the AP1130 access point is sometimes lower than what is expected or configured. |
|-----------|---|

Addressed Issues in HiveOS 8.4r10a

| | |
|-----------|--|
| HOS-15004 | ICMP exchanges were not occurring properly, resulting in a network health score of zero. |
|-----------|--|

Addressed Issues in HiveOS 8.4r10

| | |
|-----------|---|
| HOS-14756 | Administrators were sometimes unable to update the firmware on AP150W access points. |
| CFD-3858 | When disabled, the embedded web server continued to respond on the mgt0 interface. |
| CFD-3836 | Remote AP250 access points were unable to join domains. |
| CFD-3812 | AP configured to use aggregate Ethernet interfaces require 802.11at power, but were reporting using only 802.11a power, which resulted in unstable client connectivity. |
| CFD-3730 | AP250 access points acting as RADIUS servers were sometimes generating excessive Kerberos frames attempting to authenticate as root. |

Addressed Issues in HiveOS 8.4r9a

There are no addressed issues in HiveOS 8.4r9a.

Addressed Issues in HiveOS 8.4r9

| | |
|----------|--|
| CFD-3817 | Some HiveOS device interfaces were reporting the Wi-Fi connection status using G for gigahertz instead of GHz. |
|----------|--|

Addressed Issues in HiveOS 8.4r8

There are no addressed issues in HiveOS 8.4r8.

Addressed Issues in HiveOS 8.4r7

| | |
|----------|---|
| CFD-3599 | When employing GRE tunnels, AP250 and AP550 access points sometimes exhibited high CPU utilization. |
| CFD-3516 | When queried at the command line, CRC error rate value appeared incorrectly formatted. |

Addressed Issues in HiveOS 8.4r6

There are no addressed issues in HiveOS 8.4r6.

Addressed Issues in HiveOS 8.4r5

| | |
|----------|--|
| CFD-3574 | Client devices sometimes lost the 2.4 GHz connection to the AP150W access points to which they were associated. |
| CFD-3561 | APs consistently reported an incorrect CRC error rate. |
| CFD-3549 | After a successful registration, HiveOS displayed a page indicating a successful login, rather than a successful registration, sometime accompanied by error messages on some devices. |
| CFD-3535 | HiveOS did not send user account description content to HiveManager. |
| CFD-3528 | HiveOS reported the incorrect EIRP power value. |
| CFD-3459 | Some 64-bit SNMP values were truncated to 32-bit values, removing the high-order bits. |

Addressed Issues in HiveOS 8.4r4

| | |
|----------|--|
| CFD-3511 | When an admin entered the <code>show station</code> command with ARP proxy disabled, the IP address of client devices that were connecting with static IP address appeared as 0.0.0.0. |
| CFD-3503 | Administrators were unable to configure a static IP address using the NetConfig UI. |
| CFD-3461 | Some outbound traffic to international subnets contained the IP address of the AP as the source address. |
| CFD-3439 | SNMP did not function properly after rebooting the device when the SNMP server was configured to use the domain name. |
| CFD-3414 | UPA (Use Policy Acceptance) authentication did not work properly when also using PPSK. |
| HOS-8829 | Radios sometimes did not correctly report power levels on the 5 GHz band. |

Addressed Issues in HiveOS 8.4r3

| | |
|-----------|---|
| CFD-3265 | Devices did not reliably forward fragmented DNSv6 packets to wireless clients. |
| HOS-13834 | A device operating in client mode using dual 5 GHz radios sometimes assigned both radios to the same channel. |

Addressed Issues in HiveOS 8.4r2

There are no addressed issues in HiveOS 8.4r2.

Addressed Issues in HiveOS 8.4r1

This is the inaugural release of HiveOS 8.4.