

# HiveOS 8.4r6 Release Notes

**Release date:** October 17, 2018

**Release versions:** HiveOS 8.4r6

**Hardware platforms supported:** Atom AP30, AP122, AP122X, AP130, AP150W, AP230, AP245X, AP250, AP550 and AP1130

**Management platforms supported:** HiveManager 18.10.1.1 or later

---

## Change in Behavior or Appearance

This release introduces the following changes in behavior or appearance:

**CAPWAP Events Enabled for BLE Data:** This release enables CAPWAP events for BLE data by default.

---

## Known and Addressed Issues

### Known Issues in HiveOS 8.4r6

There are no known issues in HiveOS 8.4r6

### Addressed Issues in HiveOS 8.4r6.

There are no addressed issues in HiveOS 8.4r6.

## Addressed Issues in HiveOS 8.4r5.

CFD-3574	Client devices sometimes lost 2.4 GHz connection to the AP150W access points to which they were associated.
CFD-3561	APs consistently reported an incorrect CRC error rate.
CFD-3549	After a successful registration, HiveOS displayed a page indicated a successful login, rather than a successful registration, sometime accompanied by error messages on some devices.
CFD-3535	HiveOS did not send user account description content to HiveManager.
CFD-3528	HiveOS reported the incorrect EIRP power value.
CFD-3459	Some 64-bit SNMP values were truncated to 32-bit values, removing the high-order bits.

## Addressed Issues in HiveOS 8.4r4.

CFD-3511	When an admin entered the <code>show station</code> command with ARP proxy disabled, the IP address of client devices that were connecting with static IP address appeared as 0.0.0.0.
CFD-3503	Administrators were unable to configure a static IP address using the NetConfig UI.
CFD-3461	Some outbound traffic to international subnets contained the IP address of the AP as the source address.
CFD-3439	SNMP did not function properly after rebooting the device when the SNMP server is configured to use the domain name.
CFD-3414	UPA (Use Policy Acceptance) authentication does not work properly when also using PPSK.
HOS-8829	Radios sometimes did not correctly report power levels on the 5 GHz band.

## Addressed Issues in HiveOS 8.4r3.

CFD-3265	Devices did not reliably forward fragmented DNSv6 packets to wireless clients.
HOS-13834	A device operating in client mode using dual 5 GHz radios sometimes assigned both radios to the same channel.

## Addressed Issues in HiveOS 8.4r2

There are no addressed issues in HiveOS 8.4r2.

## Addressed Issues in HiveOS 8.4r1

This is the inaugural release of HiveOS 8.4.