

IQ Engine 10.1r2a Release Notes

Release date: March 11, 2020

Hardware platforms supported: AP305C, AP305CX, AP410C, and AP410CX

Management platforms supported: ExtremeCloud IQ 20.2.1.1 and later

New Features and Enhancements

This is a maintenance release and does not contain new features.

Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.1.

Known Issues in IQ Engine 10.1r2a

| | |
|-----------|---|
| HOS-15762 | The interference value sometimes differs from the real-time interference channel utilization value. |
|-----------|---|

Addressed Issues in IQ Engine 10.1r2a

| | |
|-----------|--|
| APC-35302 | A radio signal misalignment sometimes reduced network performance. |
|-----------|--|

Addressed Issues in IQ Engine 10.1r2

| | |
|----------|---|
| CFD-4453 | Disconnecting a client from a WPA3 SSID caused all other clients to disconnect. |
|----------|---|

Addressed Issues in IQ Engine 10.1r1

| | |
|----------|--|
| CFD-4300 | When an AP underwent a scheduled reboot, client devices were disconnected from the wireless network. |
|----------|--|