

IQ Engine 10.2r1 Release Notes

Release date: August 9, 2020

Hardware platforms supported: AP305C, AP305CX, AP410C, AP460C, AP510C, AP510CX, AP630, AP650, AP650X

Management platforms supported: ExtremeCloud IQ 20.7.1.1 and later

New Features and Enhancements

This release introduces the following new features and enhancements:

New Hardware Support: IQ Engine 10.2r1 supports the AP460S6C and AP460S12C access points.

Known and Addressed Issues

The following tables list known and addressed issues in IQ Engine 10.2.

Known Issues in IQ Engine 10.2r1

HOS-16248	Zero-wait DFS does not function properly on AP410C and AP510C access points.
HOS-15846	When an IDP scan is initiated, the AP sometimes stops receiving traffic from client stations.
HOS-14251	Stations sometimes cannot reconnect after DFS event.

Addressed Issues in IQ Engine 10.2r1

This is the inaugural release of IQ Engine 10.2.