

HiveOS 6.9r4 Release Notes

Release date: January 24, 2019

Hardware platforms supported: XR200P

Management platforms supported: HiveManager NG 19.1.1.1 and later

New Features and Enhancements

This release introduces the following new features and enhancements:

WebUI Disable Enhancement: You can now disable the WebUI interface without disabling the captive web portal with it.

Multiple WAN Support Improvements: HiveOS 6.9r4 includes support for configuring the XR200P router to use multiple PPPoE WAN links; for example, you can now connect two separate WAN interfaces to two separate DSL links.

Known and Addressed Issues

The following tables list known and addressed issues in HiveOS 6.9.

Known Issues in HiveOS 6.9r4

There are no known issues in this release.

Addressed Issues in HiveOS 6.9r4

| | |
|-----------|---|
| CFD-3858 | When disabled, the embedded Web server continued to respond on mgt0. |
| HOS-14778 | There was no USB interface in the WAN throughput widget. |
| HOS-14777 | VPN tunnels sometimes did not function properly when the tunnel metric was 10 or greater. |
| HOS-14768 | NAT did not function properly after uploading a complete configuration. |

Addressed Issues in HiveOS 6.9r3a

| | |
|----------|---|
| CFD-3434 | After upgrading from HiveOS 6.9r2 to HiveOS 6.9r3, XR200P routing policies did not function properly, causing traffic to be routed incorrectly. |
|----------|---|

Addressed Issues in HiveOS 6.9r3

There are no addressed issues in HiveOS 6.9r3.

Addressed Issues in HiveOS 6.9r2

There are no addressed issues in HiveOS 6.9r2.

Addressed Issues in HiveOS 6.9r1

This was the inaugural release of HiveOS version 6.9.