

FASTPATH SMB 8.2.0.2 v1.0.1.28 Release Notes

Release date: October 24, 2019

Hardware platforms supported: SR2208P, SR2224P, SR2248P, SR2324P, SR2348P

Management platforms supported: ExtremeCloud IQ 19.11.1.1 and later

New Features and Enhancements

This release introduces the following new features and enhancements:

IQ Agent Support: This release of FastPath SMB includes support for IQAgent 1.1.29.

Known and Addressed Issues

The following tables list known and addressed issues in FASTPATH SMB 8.2.0.2 v1.0.1.28:

Known Issues in v1.0.1.28

There are no known issues in this release

Addressed Issues in v1.0.1.28

CFD-4323	Issuing a reload command to a switch sometimes resulted in multiple switches in the same broadcast domain losing connectivity due to a rapid increase in broadcast traffic.
----------	---

Upgrade Process

To upgrade the FASTPATH software on your switch, establish a TFTP service that provides access to the software image, and then enter the following commands at the CLI interface:

```
(AH Switch) # copy tftp://192.168.1.127 v1.0.1.28_20191024.stk active (backup)
(AH Switch) # boot system active (backup)
(AH Switch) # reload
```

After the switch reboots, enter the following to verify the new software version:

```
User: admin
Password: aerohive
(AH Switch) > enable
(AH Switch) # show version
```